

SITE INSPECTION REVIEW FORM

SITE NAME: U.S. Pipe and Foundry

ALIASES: \_\_\_\_\_

SITE I.D.#: NJD002347565

<u>ITEM</u>	<u>COMPLETE</u> <u>YES</u>	<u>?</u> <u>NO*</u>
SITE LOCATION (INCLUDING MAP)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
SITE BACKGROUND	<input checked="" type="checkbox"/>	<input type="checkbox"/>
ENVIRONMENTAL SETTING (GEOLOGY, HYDROLOGY, METEOROLOGY, ECOLOGY + LAND USE)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
WASTE DESCRIPTION (PRESENCE + CONDITION OF WASTE + WASTE MANAGEMENT UNITS)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
LABORATORY RESULTS (CORRELATED TO SAMPLE LOCATION MAP)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
HRS PRE - SCORE (PRELIMINARY + PROJECTED)	<input type="checkbox"/>	<input checked="" type="checkbox"/>
POTENTIAL FOR DIRECT CONTACT	<input type="checkbox"/>	<input checked="" type="checkbox"/>
CONCLUSIONS + RECOMMENDATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>
REFERENCES	<input type="checkbox"/>	<input type="checkbox"/>

HRS PRE-SCORE: PRELIMINARY SCORE = 29.06

PROJECTED SCORE = \_\_\_\_\_



COMMENTS:

Site was submitted for NPL Update  
#7, no time for QA

Site has an unlined LF. Site has a NJPDES permit.  
for discharge to river, SLF & sewer.  
analysis failed QA/QC for most part.

REVIEWED BY: \_\_\_\_\_

DATE: \_\_\_\_\_

\*IF ANY ITEM IS LACKING INFORMATION PLEASE DESCRIBE IN COMMENTS